



BMW Annual Report Details

Application Id: 7535334

Particulars of the Occupier	
Annual report submit for year:	2020
Name of the authorized person:	Manish Gupta
Name of HCF or CBMWTF:	COLUMBIA ASIA HOSPITALS PVT LTD
Address for Correspondence:	BLOCK F PALAM VIHAR GURGAON
Address of Facility:	BLOCK F PALAM VIHAR GURGAON
Tel. No.:	9643657023
Fax. No.:	-
E-mail ID:	ram.u@columbiaindiahospitals.com
URL of Website:	http://www.columbiaasia.com
GPS coordinates of HCF of CBMWTF:	28.5091N 77.0416E
Ownership of HCF or CBMWTF:	Private
Status of Authorization under the BMW (Management and Handing) Rules:	
Authorization No.:	BMW19GUNO6461332
Valid Upto:	31/03/2022
Status of Consents under Water Act and Air Act.:	
Valid Upto:	31/03/2023

Health Care Facilities Details	
HCF/CBMWTF Type:	HCF
No. of Beds(for Bedded Hospital):	90
Non-Bedded Hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other):	NA
Licence Number:	6461332
Licence date of expiry:	31/03/2022

Quantity of Waste Generated	
Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	
Yellow Category:	1173
Red Category:	1441
White Category:	60
Blue Category:	420
General Solid Waste:	0

Storage, Treatment, Transportation, Processing and Disposal Facility Details	
Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	0

No of vehicles used for collection and transportation of BMW:	1
Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	Biotic Biomedical waste ltd.(Vulcan waste management)
Details of the on-site storage facility:	
Size:	216 SQ FT
Capacity:	GURGAON
Provision of on-site storage:	Seprate Closed Room with A/C

Disposal Facility			
Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)
List is Empty			

Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum		
Type of waste	Quantity Generated	Where disposal
List is Empty		

BMW Management Committee	
Do you have BMW management committee:	no

Training Conducted on BMW Details	
Number of training conducted on BMW Management:	12
Number of personnel trained:	120
Number of personnel trained at the time of induction:	100
Number of personnel not undergone any training so far:	0
Whether standard manual for training is available:	yes
Any other information:	NA

Details of the accident occurred	
No. of accident occurred:	0
Number of the persons affected:	0
Remedial Action taken:	0
Any Fatality occurred, details:	0

Other Details	
Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	0
Details of Continuous online emission monitoring systems installed:	0
Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	0

It the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	0
Any other relevant information:	0
