Form IV (See Rule 13) ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier health care facility(HCF), or common bio-medical waste treatment facility (CBWTF)]

Return No: 454788 **Period:** 2019

1. Poutieulous of the Occurries					
1. Particulars of the Occupier (i) Name of the authorized person (Occupier or operator of	Manish Trivedi				
facility):	Manush Triveat				
(ii) Name of HCF or CBMWTF:	Manipal Hospital				
(iii) Address for Correspondence:	264/1 Dr.E.Borges Road,Dona Paula Goa				
(iv) Address of Facility:	264/1 Dr.E.Borges Road,Dona Paula Goa				
(v) Tel. No.:	9975159992				
(vi) Fax. No.:	-				
(vii) E-mail ID:					
(viii) URL of Website:					
(ix) GPS coordinates of HCF of CBMWTF:	15.460187 Longitude: 73.813503				
(x) Ownership of HCF or CBMWTF:	Private				
(xi) Status of Authorization under the BMW (Managementand Handing) Rules:	Authorization No.: 13/803/19-PCB/Tech/21570 Valid Upto: 28/03/2021				
(xii) Status of Consents under Water Act and Air Act.:	Valid Upto: 20/12/2019				
2. Type of Health Care Facility					
HCF/CBMWTF Type:	HCF				
(i) No. of Beds(for Bedded Hospital):	280.0				
(ii) Non-Bedded Hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other):	NA .				
(iii) Licence Number:	0				
(iv) Licence date of expiry:					
3. Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	Yellow Category: 8572 Red Category: 12550 White Category: 780 Blue Category: 1850 General Solid Waste: 34800				
4. Details of the Storage, Treatment, Transportation, Processing and Disposal Facility Details					
(i) Details of the on-site storage facility:	Size: 550 Capacity: 1000 Provision of on-site storage: NIL				

(ii) Disposal Facility:		Type of Treatmen t Equipmen t	of U	nber Jnits	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annu m)		
		Autoclaves		1	550	15130		
		Needle tip cutter or destroyer	4	4	2	108		
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	0.0							
(iv) No of vehicles used for collection and transportation of BMW:	1							
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum					ntity rated	Where disposal		
				List is Empty				
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	Goa Health Monitoring Services							
5. Do you have BMW management committee:	no							
6. Training Conducted on BMW Details								
(i) Number of training conducted on BMW Management:	8							
(ii) Number of personnel trained:	36							
(iii) Number of personnel trained at the time of induction:	0							
(iv) Number of personnel not undergone any training so far:	0							
(v) Whether standard manual for training is available:	no							
(vi) Any other information:	NIL							
7. Details of the accident occurred								
(i) No. of accident occurred:	10							
(ii) Number of the persons affected:	0							
(iii) Remedial Action taken:	As per NACCO guidelines, HBsAg-TT prophylactic treatment given at time of inducation followed by complete blood profile post accident							
(iv) Any Fatality occurred, details:	NIL							
8. Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	NA NA							
Details of Continuous online emission monitoring systems installed:	NA							
9. Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	NIL							
10. Is the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	NIL							
11. Any other relevant information:	NIL							

Name and Signature of the Head of the Institution

Date :28/01/2020 **Place** : *NORTH GOA*